










ANGULAR/STRAIGHT STITCHER


This machine is most suitable for card board and corrugated boxes, using round or flat wire
Available in Arm length of
20", 30", 36", 42" & 48"
Adjustable feed upto 5/16",
speed upto 350 stitches
per minute.

N.B. : Production and Quantity vary on Size & Ply.

* The above specifications and designs may be changed without prior notice.



- | | | |
|---------------------------------|---|--|
| 1. Axis Pin for Corn | 25. Doom Nut | 47. Push Bar Front Portion |
| 2. Axis Pin Feed Lever | 26. End Plate | 48. Phleuda Nut |
| 3. Axis Pin for FS 102 | 27. Eccentric Adjuster | 49. Roller for Feeder |
| 4. Axis Pin for Cincher Lever | 28. Former Driver with Scoop Support | 50. Roller with Screw No. 71 |
| 5. Back Plate 12 X 25 | 29. Feeder Block | 51. Roller with Screw No. 81 |
| 6. Back Plate for Angular | 30. Feed Adjusting Screw | 52. Roller for Cut-Off-Slide |
| 7. Block for Screw | 31. Feeder Layer (Sun Mercil) | 53. Rebound Pawl |
| 8. Block Plate with Clutch Bolt | 32. Feeder Slide with Screw, Block & Spring | 54. Roller FS 133 |
| 9. Bevel Gear for Man Corn | 33. Former Roller | 55. Roller Feed Lever |
| 10. Cutting Knife | 34. Feed Return Spring | 56. Spout Screw |
| 11. Cutting Tube 12 X 25 | 35. Feed Spring Anchorage | 57. Screw for Loop Bar Spring |
| 12. Cincher Horn 12 X 25 | 36. Gripper Block | 58. Slider with Adjusting Nut & Roller |
| 13. Cincher Horn Angular | 37. Loop Bar 12 X 25 | 59. Spring FS 101 |
| 14. Cut-Off-Side | 38. Loop Bar Supporter | 60. Stop Pin for Spring |
| 15. Corn Plate | 39. Layer for Feeder (Small Link) | 61. Spring for Cut-Off-Side |
| 16. Clutch Spring | 40. Loop Bar Spring | 62. Stand for Wire Spool |
| 17. Clutch Sleeve | 41. Long Screw | 63. Feedle Spring |
| 18. Clutch Pawl | 42. Looking Spring AS 129 | 64. Top Stud |
| 19. Connecting Link | 43. Looking Spring AS 130 | 65. V-Belt Pulley 7" Dia |
| 20. Cincher Corn | 44. Looking Handle | 66. Wire Guide |
| 21. Cincher Lever with Bolt | 45. Motor Pulley | 67. Wire Gripper |
| 22. Centre Pin for Spring | 46. Mort. Corn with Bevel | 68. Wire Guide Spring |
| 23. Cincher Die for Bottom | | 69. Wire Holder with Spring |
| 24. Driver 12 X 25 | | 70. Wire Sock |



1. Axis Pin for Cam
2. Feed Spring Achorage
3. Feed Return Spring
4. Wire Guide Spring
5. Axis Pin Feed Lever
6. Feed Lever (Gun Metal)
7. Stop Pin for Spring
8. Locking Spring AS 1 30
9. Slider with Adjusting Nut & Roller
10. Feed Adjusting Screw
11. Locking Spring AS 1 29
12. Block for Screw
13. Roller with Screw No. 71
14. Roller with Screw No. 81
15. Feeder Block
16. Feeder Slide with Screw Block & Spring
17. Gripper Block
18. Oil Cup
19. Doom Nut
20. Main Cam with Bevel
21. Connecting Link
22. Main Head without Cover Plate
23. Cut-Off-slide
24. Former Driver with Stapple Support
25. Driver 1 2 X 25
26. Spring for Cut-Off-slide
27. Centre Pin for Spring
28. Cam Plate
29. Cutting Knife
30. Cutting Tube 1 2 X 25